

Fitness Certificate of School Building


To be filled by the Inspecting Officer (Asst. Engineer)

- 1 Name of the officer **Smt.Ammu Chandran**
- 2 Name of School **RAJAGIRI AMALA CMI PUBLIC SCHOOL**
- 3 Location with name of Edn. Dist./Sub.Dist. **KADUTHURUTHI,VAIKOM**
- Classification of building as specified in column of the application for fitness certificate and size
- 1) **BLOCK-A 27.80x18.50x10.80 M**
- 2) **RCC 3 Storey building**
- 3) **3x6x6.60x6.60 - Class rooms**
- 4 Classification of building and size
- i. Permanent (Single or Multi storeyed) **3 storeyed**
- ii. Semi permanent
- iii. Temporary shed
- 5 Period of witch the certificate is issued **2023-24**
- 6 Name of defect if any
- a. Foundation and basement
- b. Superstructure
- c. Doors and windows
- d. Roof
- e. Flooring
- f. Miscellaneous(cracks etc.)
- NIL**
- 7 Any major defects noticed which will render the building unsafe if any manner
- 8 Whether maintenance work have been done properly **yes**
- 9 Whether the structure is sound or not for conducting classes **The structure is sound in normal weather condition.**
1. The stability of the structure should be examined also with reference to location attitude intensityof wind,exposure to flood etc.
2. Any additional observations if deemed for the certificate may be furnished seperatly with the certificate.

Certified that the anganwadi was inspected by me on 19-06-2023 and found to be fit to conduct classes for the period 1-6-2023 to 31-5-2024 for the reason stated above.

Place - tv puram

Date -20-06-2023.



Signature

Designation


Ammu Chandran
Assistant Engineer
LID & EW Section
T.V Puram Grama Panchayath

Fitness Certificate of School Building

To be filled by the Inspecting Officer (Asst. Engineer)

- 1 Name of the officer **Smt.Ammu Chandran**
- 2 Name of School **RAJAGIRI AMALA CMI PUBLIC SCHOOL**
- 3 Location with name of Edn. Dist./Sub.Dist. **KADUTHURUTHI,VAIKOM**
- Classification of building as specified in column of the application for fitness certificate and size
- 1) **BLOCK-B 27.80x19.25x7.00 M**
- 2) **RCC 2 Storey building**
- 4 Classification of building and size
- i. Permanent (Single or Multi storeyed) **2 storeyed**
- ii. Semi permanent
- iii. Temporary shed
- 5 Period of witch the certificate is issued **2023-24**
- 6 Name of defect if any
- a. Foundation and basement
- b. Superstructure
- c. Doors and windows
- d. Roof
- e. Flooring
- f. Miscellaneous(cracks etc.)
- NIL**
- 7 Any major defects noticed which will render the building unsafe if any manner
- 8 Whether maintenance work have been done properly **yes**
- 9 Whether the structure is sound or not for conducting classes **The structure is sound in normal weather condition.**
1. The stability of the structure should be examined also with reference to location attitude intensityof wind,exposure to flood etc.
2. Any additional observations if deemed for the certificate may be furnished seperatly with the certificate.

Place - tv puram
Date -20-06-2023.



Signature
Designation

Ammu
Assistant Engineer,
LID & EW Section
T.V Puram Grama Panchayath

Fitness Certificate of School Building

To be filled by the Inspecting Officer (Asst. Engineer)

- 1 Name of the officer **Smt.Ammu Chandran**
- 2 Name of School **RAJAGIRI AMALA CMI PUBLIC SCHOOL**
- 3 Location with name of Edn. Dist./Sub.Dist. **KADUTHURUTHI,VAIKOM**
- Classification of building as specified in column of the application for fitness certificate and size **1) BLOCK-C 30x16.40x7.00 M
2) RCC 2 Storey building**
- 4 Classification of building and size
- i. Permanent (Single or Multi storeyed) **2 storeyed**
- ii. Semi permanent
- iii. Temporary shed
- 5 Period of witch the certificate is issued **2023-24**
- 6 Name of defect if any
- a. Foundation and basement
- b. Superstructure
- c. Doors and windows
- d. Roof
- e. Flooring
- f. Miscellaneous(cracks etc.)
- NIL**
- 7 Any major defects noticed which will render the building unsafe if any manner
- 8 Whether maintenance work have been done properly **yes**
- 9 Whether the structure is sound or not for conducting classes **The structure is sound in normal weather condition.**
1. The stability of the structure should be examined also with reference to location attitude intensityof wind,exposure to flood etc.
2. Any additional observations if deemed for the certificate may be furnished seperatly with the certificate.

Certified that the anganwadi was inspected by me on 19-06-2023 and found to be fit to conduct classes for the period 1-6-2023 to 31-5-2024 for the reason stated above.

Place - tv puram
Date -20-06-2023.

Signature
Designation

Assistant Engineer
LID & EW Section
T.V Puram Grama Panchayath

