Fitness Certificate of School Building

To be filled by the Inspecting Officer (Asst. Engineer) (Re: GOMs. 20/70/PWD Dt.23-01-1970)

1 Name of the officer

Smt.Ammu Chandran

2 Name of School

Rajagiri amala CMI public school

3 Location with name of Edn. Dist./Sub.Dist. Classification of building as specified in column of the application for

Kaduthuruthi ,vaikom

fitnesscertificate and size

1) Block B 27.80X19.25X7.00M

2) RCC 2 storey building

4 Classification of building and size

i. Permannent (Single or Multi storeyed)

2 storeyed

ii. Semi permannent

iii. Temporary shed

5 Period of witch the certificate is issued

2024 - '25

6 Name of defect if any

a. Foundation and basement

b. Superstructure

c. Doors and windows

d. Roof

e. Flooring

f. Miscellaneous(cracks etc.)

7 Any major defects noticed which will render the building unsafe if any manner

8 Whether maintenance work have been done properly

YES

9

The structure is sound under normal weather condition for conducting classes

Whether the structure is sound or not for conducting classes

Note:-

1. The stability of the structure should be examined also with reference to location attitude

2. Any additional observations if deemed for the certificate may be furnished seperatly with the Certified that the school was inspected by me on21-05-2024 and found to be fit

to conduct classes for the period 1-6-2024to 31-5-2025 for the reason stated above

Place - TV Puram.

Date - 14-06-2024.

Signature Designation

LID & EW Section T.V Puram Grama Panchayath



Fitness Certificate of School Building

To be filled by the Inspecting Officer (Asst. Engineer) (Re: GOMs. 20/70/PWD Dt.23-01-1970)

1 Name of the officer

Smt.Ammu Chandran

2 Name of School

Rajagiri amala CMI public school

3 Location with name of Edn. Dist./Sub.Dist. Classification of building as specified in column of the application for fitnesscertificate and size

Kaduthuruthi ,vaikom

- 1) Block A 27.80X18.50X10.80
- 2) RCC 3 storey building
- 3) 3X6x6.60x6.60-class rooms

4 Classification of building and size

i. Permannent (Single or Multi storeyed)

ii. Semi permannent

iii. Temporary shed

5 Period of witch the certificate is issued

6 Name of defect if any

- a. Foundation and basement
- b. Superstructure
- c. Doors and windows
- d. Roof
- e. Flooring
- f. Miscellaneous(cracks etc.)
- 7 Any major defects noticed which will render the building unsafe if any manner
- 8 Whether maintenance work have been done properly

Three storeyed

2024 - '25

YES

Whether the structure is sound or not for conducting classes

The structure is sound under normal weather condition for conducting classes

Note:-

9

- 1. The stability of the structure should be examined also with reference to location attitude
- 2. Any additional observations if deemed for the certificate may be furnished seperatly with the Certified that the school was inspected by me on21-05-2024 and found to be fit

to conduct classes for the period 1-6-2024to 31-5-2025 for the reason stated above Place - TV Puram,

Date - 14-06-2024.

Signature

Designation

LID & EW Section T.V Puram Grama Panchayath

Fitness Certificate of School Building

To be filled by the Inspecting Officer (Asst. Engineer) (Re: GOMs. 20/70/PWD Dt.23-01-1970)

1 Name of the officer

Smt.Ammu Chandran

2 Name of School

Rajagiri amala CMI public school

3 Location with name of Edn. Dist./Sub.Dist. Classification of building as specified in column of the application for

Kaduthuruthi vaikom

fitnesscertificate and size

1) Block C 30X16.40X7.00M

2) RCC 2 storey building

4 Classification of building and size

i. Permannent (Single or Multi storeyed)

2 storeyed

ii. Semi permannent

iii. Temporary shed

5 Period of witch the certificate is issued

2024 - '25

6 Name of defect if any

a. Foundation and basement

b. Superstructure

c. Doors and windows

d. Roof

e. Flooring

f. Miscellaneous(cracks etc.)

7 Any major defects noticed which will render the building unsafe if any manner

8 Whether maintenance work have been done properly

YES

The structure is sound under normal weather condition for conducting classes

Whether the structure is sound or not for conducting classes

Note:-

1. The stability of the structure should be examined also with reference to location attitude

2. Any additional observations if deemed for the certificate may be furnished seperatly with the Certified that the school was inspected by me on21-05-2024 and found to be fit

to conduct classes for the period 1-6-2024to 31-5-2025 for the reason stated above

Place - TV Puram,

Date - 14-06-2024.

Signature Designation

LIU & LW Section Panchayath