Fitness Certificate of School Building

To be filled by the Inspecting Officer (Asst. Engineer) (Re: G O Ms. 20/70/PWD Dt.23-01-1970)

- 1 Name of the officer
- 2 Name of School
- 3 Location with name of Edn. Dist./Sub.Dist.

 Classification of building as specified in column of the application for fitness certificate and size

Smt.MEEDIARANI.S

Rajagiri amala CMI public school KADUTHURUTHY, VAIKOM

- 1) Block A 27.80X18.50X10.80 3X6X6.06X6.60-class room
- 2) RCC 3 storey building
- 4 Classification of building and size

i. Permannent (Single or Multi storeyed)

Three storeyed

ii. Semi permannent

iii. Temporary shed

5 Period of witch the certificate is issued

2025-26

6 Name of defect if any

- a. Foundation and basement
- b. Superstructure
- c. Doors and windows
- d. Roof
- e. Flooring
- f. Miscellaneous(cracks etc.)
- 7 Any major defects noticed which will render the building unsafe if any manner
- 8 Whether maintenance work have been done properly

NIL

yes


Whether the structure is sound or not for conducting classes

The structure is sound in normal weather condition.

- 1. The stability of the structure should be examined also with reference to location attitude intensity of wind, exposure to flood etc.
- 2. Any additional observations if deemed for the certificate may be furnished seperatly with the certificate.

Certified that the school was inspected by me on 29-07-2025 and found to be fit to conduct classes for the period 1-8-2025 to 31-7-2026 for the reason stated above.

Place - Tv puram Date -30-07-2025.



Signature Designation

e Assistant Engineer
on LID & EW Section
T.V Puram Grama Panchayath

Fitness Certificate of School Building

To be filled by the Inspecting Officer (Asst. Engineer) (Re: G O Ms. 20/70/PWD Dt.23-01-1970)

1 Name of the officer

2 Name of School

3 Location with name of Edn. Dist./Sub.Dist. Classification of building as specified in column of the application for fitness certificate and size Smt.MEEDIARANI.S

Rajagiri amala CMI public school KADUTHURUTHY, VAIKOM

- 1) Block C 30X16.40X7.00M
- 2) RCC 2storey building

4 Classification of building and size

i. Permannent (Single or Multi storeyed)

2 storeyed

ii. Semi permannent

iii. Temporary shed

5 Period of witch the certificate is issued

2025-26

6 Name of defect if any

a. Foundation and basement

b. Superstructure

c. Doors and windows

d. Roof

e. Flooring

f. Miscellaneous(cracks etc.)

7 Any major defects noticed which will render the building unsafe if any manner

8 Whether maintenance work have been done properly

NIL

yes


Whether the structure is sound or not for conducting classes

The structure is sound in normal weather condition.

- 1. The stability of the structure should be examined also with reference to location attitude intensity of wind, exposure to flood etc.
- 2. Any additional observations if deemed for the certificate may be furnished seperatly with the certificate.

Certified that the school was inspected by me on 29-07-2025 and found to be fit to conduct classes for the period 1-8-2025 to 31-7-2026 for the reason stated above.

Place - Tv puram Date -30-07-2025.



Signature Designation ,

ASSISTANT Ensetion
LID & EW Section
T.V Puram Grama Panchayath

Fitness Certificate of School Building

To be filled by the Inspecting Officer (Asst. Engineer) (Re: G O Ms. 20/70/PWD Dt.23-01-1970)

1 Name of the officer

2 Name of School

3 Location with name of Edn. Dist./Sub.Dist.

Classification of building as specified in column of the application for fitness certificate and size

Smt.MEEDIARANI.S

Rajagiri amala CMI public school KADUTHURUTHY, VAIKOM

1) Block B 27.80X19.25X7.00M

2) RCC 2storey building

4 Classification of building and size

i. Permannent (Single or Multi storeyed)

2 storeyed

ii. Semi permannent

iii. Temporary shed

5 Period of witch the certificate is issued

2025-26

6 Name of defect if any

a. Foundation and basement

b. Superstructure

c. Doors and windows

d. Roof

e. Flooring

f. Miscellaneous(cracks etc.)

7 Any major defects noticed which will render the building unsafe if any manner

8 Whether maintenance work have been done properly

NIL

ves


Whether the structure is sound or not for conducting classes

The structure is sound in normal weather condition.

- 1. The stability of the structure should be examined also with reference to location attitude intensity of wind, exposure to flood etc.
- 2. Any additional observations if deemed for the certificate may be furnished seperatly with the certificate.

Certified that the school was inspected by me on 29-07-2025 and found to be fit to conduct classes for the period 1-8-2025 to 31-7-2026 for the reason stated above.

Place - Tv puram Date -30-07-2025.



Signature Assistant Engineer
Designation LID & EW Section
T.V Puram Grama Panchayath